## 15 Kg-cm

## TORQUE METER

Model: TQ-8800 *ISO-90* 

ISO-9001, CE, IEC1010



## **FEATURES**

- \* Professional torque meter with 15 Kg-cm torque probe, full set.
- \* 3 kind display unit : Kg-cm, Kg-cm, LB-inch and Newton-cm.
- \* Peak value measurement.
- \* Data hold.
- \* Peak hold measurement.
- \* High/Low resolution button.
- \* Fast/Low sampling button.
- \* Record Max. and Min. readings.
- \* RS 232 computer interface.
- \* Super large LCD display.
- \* Microcomputer circuit.
- \* Separate torque probe, easy operation.
- \* Auto shut off saves battery life.
- \* Built-in low battery indicator.
- \* Heavy duty & compact housing case.
- \* Supply with the hard carrying case.





The Art of Measurement

## **TORQUE METER, 15 Kg-cm**

Model: TQ-8800

FEATURES				
* Professional torque meter with 15 Kg-cm torque	* Record Maximum and Minimum readings with			
probe, full set.	recall.			
* 3 kind display unit select button of Kg-cm,	* RS 232 computer interface.			
LB-inch and Newton-cm in the front panel.	* Super large LCD display, easy readout.			
* Peak value measurement	* Microcomputer circuit, high performance.			
* Data hold button to freeze the desired reading.	* Separate torque probe, easy operation.			
* Peak hold measurement to hold the peak value.	* Auto shut off saves battery life.			
* High/Low resolution select by push button.	* Built-in low battery indicator.			
* Fast/Low sampling select by push button.	* Heavy duty & compact housing case.			
	* Complete set with the hard carrying case.			

	GENERAL SPE	CIFICATIONS		
Display	61 mm x 34 mm supper large	Power supply	Alkaline or heavy duty type	
	LCD display.		DC 9V battery, 006P,	
	15 mm ( 0.6" ) digit size.		MN1604 (PP3) or equivalent.	
Measurement	Torque value, peak hold,	Power consumption	Approx. DC 20 mA.	
	data hold, Max. & min. value.	Weight	Meter 230 g ( 0.50 LB ).	
Display unit	Kg-cm/LB-inch/Newton-cm.		<i>Probe</i> 600 g ( 1.32 LB )	
Sensor	Exclusive torque sensor.	Chuck head	1/2 to 20 UNF,	
Circuit	Exclusive microcomputer	size	1.5 to 13 mm,	
	circuit.	Dimension	Meter :	
Data hold	Freeze the desired reading.		180 x 72 x 32 mm	
Peak hold	To hold the peak value.		(7.1 x 2.8 x1.3 inch).	
Memory	Maximum & Minimum value.		Torque probe:	
Power off	Auto shut off, saves battery life,		Round 48 mm Dia. x 160 mm.	
	or manual off by push button.	Accessories	Instruction manual 1 PC.	
Sampling time	Fast/Slow select.	included	15 Kg torque probe1 PC.	
Data output	RS 232 serial output.		Carrying Case 1 PC.	
Sensor type	To confirm the sensor type exactly	.Optional	* Software ( Windows version,	
button		accessories	data record & data	
Operating	$0^{\circ}\!$		acquisition )SW-U801-WIN	
temperature			* RS232 cableUPCB-01	
Operating	Less than 80% RH.		* USB cableUSB-01	
humidity				

DISPLAY UNIT/RESOLUTION							
Unit	Max. range	High resolution	Low resolution	Over load protection range			
Kg-cm	15 Kg-cm	0.01 kg-cm	0.1 Kg-cm	22.5 Kgf-cm max.			
LB-inch	12.99 LB-inch	0.01 LB-inch	0.1 LB-inch	19.53 LBf-inch max.			
Newton-cm	147.1 Newton-cm	0.1 Newton-cm	1 Newton-cm	220.1 N-cm max.			

<sup>\*</sup> Appearance and specifications listed in this brochure are subject to change without notice.